

称重传感器误差概述与分析

702

【摘要】

【关键词】

一、概述


二、称重传感器主要单项误差分析

$$\eta(\varepsilon) = \frac{\varepsilon_z - \varepsilon_0}{\varepsilon_0} = \frac{(\varepsilon_0 + 2\mu\varepsilon_0^2) - \varepsilon_0}{\varepsilon_0} = 2\mu\varepsilon_0 = 0.56\varepsilon$$

$$\eta(\varepsilon) = \frac{\varepsilon_z - \varepsilon_0}{\varepsilon_0} = \frac{(\varepsilon_0 - 2\mu\varepsilon_0^2) - \varepsilon_0}{\varepsilon_0} = -2\mu\varepsilon_0 = -0.56\varepsilon$$

$$\eta(\varepsilon) = \frac{\varepsilon_z - \varepsilon_0}{\varepsilon_0} = -\frac{48P^2L^5}{5E^2b^2h^6}$$


$$\frac{\Delta R}{R} = \varepsilon_R = CK\varepsilon$$



三、称重传感器温度误差分析

$$\frac{\Delta S_t}{S} = \gamma - 2\alpha_L - \beta_E$$

四、建立数学模型分析称重传感器的温度误差



$$R_i = R + r_i$$

$$U_0 = \frac{R_1 R_3 - R_2 R_4}{(R_1 + R_2)(R_3 + R_4)} \cdot U_i$$

$$U_0 = \frac{(R+r_1)(R+r_3) - (R+r_2)(R+r_4)}{(2R+r_1+r_2)(2R+r_3+r_4)} \cdot U_i$$

$$U_0 = \frac{\frac{R^2 r_1}{R} + \frac{R^2 r_3}{R} + r_1 r_3 - \frac{R^2 r_2}{R} - \frac{R^2 r_4}{R} - r_2 r_4}{4R^2 + 2R(r_1 + r_2 + r_3 + r_4) + (r_1 + r_2)(r_3 + r_4)} \cdot U_i$$

$$r'_1 = \frac{r_1}{R} \quad r'_2 = \frac{r_2}{R} \quad r'_3 = \frac{r_3}{R} \quad r'_4 = \frac{r_4}{R}$$


$$\alpha_1 = r_1 r_3 - r_2 r_4$$

$$\alpha_2 = (r_1 + r_2)(r_3 + r_4)$$

$$r_{sum} = r_1 + r_2 + r_3 + r_4$$

$$U_0 = \frac{R^2 (r'_1 + r'_3 - r'_2 - r'_4) + \alpha_1}{4R^2 + 2Rr_{sum} + \alpha_2} \cdot U_i$$

$$\varepsilon_{app} = \left[\frac{\alpha_R}{K_0} + (\alpha_m - \alpha_g) \right] \Delta T$$



$$d_{1r}(T) = A(B + b)$$

$$B = \left(\frac{T - T_c}{T_r} \right) \pi$$

$$d_{2r}(T) = mT + k$$

$$\begin{aligned}
 U_0 &= \frac{R_1 R_3 - R_2 R_4}{(R_1 + R_2)(R_3 + R_4)} \cdot U_i \\
 &= \frac{(R + \Delta R_1)(R + \Delta R_3) - (R - \Delta R_2)(R - \Delta R_4)}{(2R + \Delta R_1 - \Delta R_2)(2R + \Delta R_3 - \Delta R_4)} \cdot U_i
 \end{aligned}$$

$$U_0 = \frac{U_i}{4} \cdot \frac{\frac{\Delta R_1}{R} + \frac{\Delta R_2}{R} + \frac{\Delta R_3}{R} + \frac{\Delta R_4}{R}}{1 + \frac{1}{2} \left(\frac{\Delta R_1}{R} - \frac{\Delta R_2}{R} + \frac{\Delta R_3}{R} - \frac{\Delta R_4}{R} \right)}$$

$$\Delta R_1 = \Delta R_2 = \Delta R_3 = \Delta R_4 = \Delta R$$

$$U_0 = \frac{\Delta R}{R} U_i$$

$$U_0 \text{ 与 } \frac{\Delta R}{R}$$

$$R_t = R_0 (1 + \alpha_0 \Delta t)$$

$$\Delta R_t = R_t - R_0 = R_0 (1 + \alpha_0 \Delta t) - R_0 = R_0 \alpha_0 \Delta t$$

$$R_1 = \Delta R_1 + \Delta R_t \quad R_2 = \Delta R_2 + \Delta R_t$$

$$R_3 = \Delta R_3 + \Delta R_t \quad R_4 = \Delta R_4 + \Delta R_t$$

$$U_0 = \frac{(\Delta R_1 + \Delta R_t)(\Delta R_3 + \Delta R_t) - (\Delta R_2 + \Delta R_t)(\Delta R_4 + \Delta R_t)}{(\Delta R_1 + \Delta R_2 + 2\Delta R_t)(\Delta R_3 + \Delta R_4 + 2\Delta R_t)} \cdot U_i$$

$$U_0 = \frac{\Delta R}{R + \Delta R_t} \cdot U_i$$

$$S = \frac{e}{U} = \frac{1 + \mu}{2} \cdot \frac{K}{EA} \cdot P$$



五、结束语

[参考文献]

- 1 VISHAY.Micro- Measurements Division: Strain Gages Temperature Elect Tech Nnote, 1998
- 2 BLH.Electronics Practical Strain Gage Measurements Application Note, 1993
- 3 . C . .1990
- 4 . C .
1993
- 5 OIML R 60 1991 1993 A
- 6 OIML R 60- 1 2017 E- cn
1937—

O